

Schneider Electric
ACF400/ACF402 Rack Air Removal Unit
www.schneider-electric.com
Release Notes (990-3200-EN.txt)

Released: May 30, 2007

Affected Revision Levels:

apc_hw02_aos_314.bin	Network Management Card Operating System & TCP/IP Stack
apc_hw02_raru_311.bin	Rack Air Removal Unit

For details on upgrading the Rack Air Removal Unit's firmware, see the Installation and Operation manual on the Schneider Electric (www.schneider-electric.com) or the APC Web site (www.apc.com).

Contents:

- 1.0 OS & TCP/IP Stack Modifications (apc_hw02_aos_314.bin)
 - 1.1 COMPATIBILITY
 - 1.2 KNOWN ISSUES IN THIS VERSION
 - 1.3 NEW FEATURES & ENHANCEMENTS
 - 1.4 BUGS FIXED IN THIS VERSION
- 2.0 Rack Air Removal Unit (apc_hw02_raru_311.bin) Modifications
 - 2.1 COMPATIBILITY
 - 2.2 KNOWN ISSUES IN THIS VERSION
 - 2.3 NEW FEATURES & ENHANCEMENTS
 - 2.4 BUGS FIXED IN THIS VERSION
- 3.0 Miscellaneous
 - 3.1 RECOVERING FROM A LOST PASSWORD

1.0 OS & TCP/IP Stack Modifications (apc_hw02_aos_314.bin)

1.1 COMPATIBILITY

apc_hw02_aos_314.bin Rack Air Removal Unit

1.2 KNOWN ISSUES IN THIS VERSION

None.

1.3 NEW FEATURES & ENHANCEMENTS

1. The Network Management Card now stores the ARU downloader firmware and application firmware. Upgrade the downloader firmware first, then upgrade the ARU firmware. To upgrade the firmware using the display interface, select the Configuration screen, then select the Update Dnloadr Code screen. When the downloader firmware is upgraded, select the Configuration screen, then select the Update ARU Firmware screen.

1.4 BUGS FIXED IN THIS VERSION

None.

2.0 Rack Air Removal Unit (apc_hw02_raru_311.bin) Modifications

2.1 COMPATIBILITY

apc_hw02_aos_314.bin Network Management Card OS & TCP/IP Stack

2.2 KNOWN ISSUES IN THIS VERSION

None.

2.3 NEW FEATURES & ENHANCEMENTS

1. The display interface help indicates that the downloader firmware must be upgraded before the ARU application firmware.

2.4 BUGS FIXED IN THIS VERSION

1. Downloader firmware version 0.0 caused the processor to enter download mode and never leave, deleting the application firmware and causing the ARU fans to operate at full speed. To avoid this issue, upgrade the downloader firmware to version 1.0, then upgrade the ARU application to firmware version 3.1.5a.

3.0 Miscellaneous

3.1 RECOVERING FROM A LOST PASSWORD

See the User's Guide on the Schneider Electric (www.schneider-electric.com) or the APC Web site (www.apc.com) for instructions on how to recover from a lost password.

© 2014 by Schneider Electric. All rights reserved. Schneider Electric and InRow are owned by Schneider Electric Industries S.A.S., or their affiliated companies. All other trademarks are property of their respective owners.